




PIM Cutting

Page 1/2

Cutting off the Plug-In-Module of the beam line based on procedure [EDMS 3465793](#)

EDMS NO.	REV.	VALIDITY
3481625	1.0	VALID
REFERENCE		
FLW_PIM-CUTTING_LHC-TUNNEL		

Date: 2026-07-27



Legend

Ordinary Tasks


- | | |
|-------------------|--------------------------------------|
| Write a Document | Draw |
| Photograph / Scan | Interact with system |
| Check | Simulate |
| Analyze | Decide (one outcome) |
| Inform | Plan / Organise |
| Schedule | Handle |
| Transport | Build / Install |
| Construct | Buy |
| Operate | Maintain |
| Recycle | Train / Get trained |
| Guide / Help | Be informed |
| Sub-process | Process described in another diagram |

Decision Tasks

- | | |
|---------------------------|-------|
| Branching | → YES |
| Decide (several outcomes) | → NO |

Jumps

This notation is used when it is necessary to directly jump to a specific task without overloading the diagram with arrows. A typical use case is when it is necessary to go back to a task after a verification proved negative and that some work needs to be redone.



Process

- Event starting the process
- Pause in the process, for a given role
- End of the process
- Rewind: restart the process from the beginning



PIM Cutting

Page 2/2

Cutting off the Plug-In-Module of the beam line

Date: 2026-07-27

Management


RP

TE-MSC

QA

EN-MME

TE-VSC



Legend

Ordinary Tasks




Decision Tasks




Jumps

This notation is used when it is necessary to directly jump to a specific task without overloading the diagram with arrows. A typical use case is when it is necessary to go back to a task after a verification proved negative and that some work needs to be redone.



Process



*1 For NCR Closing please use "Close with Warning" EDMS status